

CONSUMER TECHNICAL NOTICE

INVICTUS Speargun Handle Trigger mechanisms

OMER is conducting a voluntary product update of select INVICTUS SPEARGUN parts. INVICTUS triggers are found on all OMER branded spearguns of the INVICTUS Family:

INVICTUS REX, INVICTUS HF, INVICTUS CARBON

OMER has been aware that in some very rare cases, an issue may occur during a dive, causing the INVICTUS mechanism to block and as such, not release the shaft.

OMER believes that a voluntary technical consumer notice is necessary.



INVICTUS spearguns without the mark "M" need to be serviced - Requires an Update

AQUALUNG GROUP
After sales service department
14ème Rue, 06513 Carros, France















AQUALUNG GROUP



Trigger mechanisms with the "M" have already been updated at the factory - **No further action required**

Remedy: Consumers are advised to have their INVICTUS spearguns without the "M" marks on trigger and mechanisms checked and upgraded by their nearest authorized OMER Retailer or Dive Center. Simply bring the Speargun to your nearest authorized OMER / Aqua Lung Dive Retailer or Dive Center.

Use our DEALER LOCATOR if you are not sure where your nearest dealer is: http://www.omersub.com/en/store-finder/

They will be able to update your trigger mechanisms for you. You will not incur any charges.

Consumer Contact - for additional assistance please visit: http://www.omersub.com/en/contact-us/

AQUALUNG GROUP
After sales service department
14ème Rue, 06513 Carros, France
INVICTUS TECHNICAL NOTICE Vers. B













